



Let's Measure Peat

Do you still measure the bulkdensity of your peat and substrates according to EN12580 by hand?

As many people have experienced, measuring this by hand is very time-consuming and gives results that can deviate as much as 20 percent.



last century....

The Solution

the INADCO Densimeter

Accurate and fully automatic.

Many satisfied users over the past 10 years



Various options are possible:

- Stand alone
- or combined with:
 - a printer
 - a (certified) Belt Weigher
 - a data storage device
 - a connection with your factory automation
 - moisture-measurement
 -

Contact us for more specific information or look at our website.



The yellow shovel takes samples from the belt and drops them in the black CEN Measuring Cylinder (with white bottom).

Meerheide 18 5521 DZ Eersel The Netherlands
Phone: ++31 497-517291 Fax: ++31 497-517469
Internet: www.inadco.nl E-mail: info@inadco.nl